

INFO TIPS




FUEL PRESSURE SENSOR

REF. 170070 | ADAPTABLE CONNECTOR FOR FORD & PSA SENSORS

This new **adaptable cabling** is supplied with its **corrugated sheath** and **3 heat-shrinkable end caps** with **only one connector on one side** is compatible with the **following fuel pressure sensors**:

Ref. 170070



| | Ref. 1473511 | Ref. 1473512 | Ref. 1473521 |
|--------------------------------|---|---|---|
| |  |  |  |
| OEM refs. sensor only | PSA 9676643880 | Ford 4M5Q-9D280-DB | PSA 9813735580 9664111780 1920TL |
| OEM ref. injection ramp | 9804776780 | The ramp is not detailed by the manufacturer | 1570Q4 |
| Applications | 208, 308, 2008, 3008, 5008 1.6 HDi / BlueHDi | Focus, Galaxy, Mondeo, Transit 1.8 TDCi | 208, 308, 2008, 3008, 5008 1.6 HDi |

As a reminder, the **connector** would be responsible **one third of the time** of the **origin of the failure**. In order to avoid additional costs for customers, we recommend the replacement of the **sensor AND its connector** (sold separately for previous references).



Technical hotline
+33 (0)4 72 88 12 63
hotline.aftermarket@efiautomotive.com