TECH TIPS

FUEL PRESSURE SENSOR



CONNECTOR + SENSOR KIT | ASSEMBLY RECOMMENDATIONS

Why change the sensor and its connector simultaneously?

Vehicle **vibrations** cause **wear/cracking** of the wiring harness connected to the ECU.

Consequences: **short circuits**, sporadic or missing sensor signal > erroneous data > faulty function.

The engine environment (oil, humidity, heat) causes oxidation of the connector tabs.

In order to avoid further repairs (additional costs and loss of time), we recommend replacing the sensor and its connector sold in kit (ref. 1473501K) or separately (ref. 170070 + 1473511/1473512/1473521).

1/ COMPLETE KIT (Ref. 1473501K)



2/ KITS SOLD SEPARATELY



The connector and the sensor must be purchased separately.



Technical hotline

+33 (0)4 72 88 12 63

hotline.aftermarket@efiautomotive.com