TECH TIPS FUEL PRESSURE SENSOR



CONNECTOR + SENSOR KIT | ASSEMBLY RECOMMENDATIONS

Why change the sensor and its connector simultaneously?

Vehicle **vibrations** cause **wear/cracking** of the wiring harness connected to the ECU. Consequences: **short circuits**, sporadic or missing sensor signal > erroneous data > faulty function.

The engine environment (oil, humidity, heat) causes oxidation of the connector tabs.

In order to avoid **further repairs (additional costs** and **loss of time**), we recommend **replacing the sensor and its connector** sold in **kit** (ref. **1473501K**) or **separately** (ref. **170070** + **1473511/1473512/1473521**).

1/ COMPLETE KIT (Ref. 1473501K)



2/ KITS SOLD SEPARATELY (Ref. 170070 + 1473511/1473512/1473521)





Technical hotline

+33 (0)4 72 88 12 63 hotline.aftermarket@efiautomotive.com