
TECH TIPS FUEL PRESSURE SENSOR



REF. 1473501 | ASSEMBLY RECOMMENDATION

Only the black o-ring seal must be assembled, otherwise gasoil leaks could happen. The metallic seal is for another pressure sensor assembling (OEM ref. 1920GW).





Recommended tightening torque: **45 Nm** (risk of sensor breakage and deterioration of the common rail).



Technical hotline +33 (0)4 72 88 12 63 hotline.aftermarket@efiautomotive.com