

# INFO TIPS

## EXHAUST TEMPERATURE SENSORS




REFS. 1473112, 1473116, 1473184, 1473195 | HIGH RETURN RATE

We would like to draw your attention to the high return rate (>1%) of references **1473112, 1473116, 1473184, 1473195** with a **code date prior to March 2023 (03/23)**.


### CORRECTIONS MADE

To counter this problem, we have improved the **robustness of the thermistor** on sensors with a **code date after March 2023 (03/23)**.



However, products with a **code date prior to March 2023 (03/23)** remain functional, but might have a higher return rate than our standards.

### WHERE CAN I FIND THE DATE CODE?



If you wish to return the parts, please contact  
Coralie LAMORLETTE on +33 (0)3 25 94 96 75 to find out how to proceed.



**Technical hotline**

+33 (0)4 72 88 12 63

[hotline.aftermarket@efiautomotive.com](mailto:hotline.aftermarket@efiautomotive.com)